

# PRODUCT END-OF-AVAILABILITY NOTICE

## FastIron SX Switch Fabric and Chassis Bundle

Brocade is announcing that the Brocade FastIron SX switch fabric module, and the FastIron SX chassis bundles which include the switch fabric module products will not be available for importing into the European Union after June 30, 2016. Effective July 21, 2016, EU RoHS exemption 7b expires and a subset of exemption 11 is expected to expire impacting the Brocade FastIron SX switch fabric module, and the FastIron SX chassis bundles which include the switch fabric module products. These products will not be ROHS 2016 compliant. This event is triggering an early Last Customer Ship (LCS) announcement of these products in the European Union.

Please note this does not affect shipments to Americas, APAC or the rest of EMEA.

Brocade will continue to offer and provide Software support for those customers with a valid support contract for the EOA products until formal notification of the End of Support of the entire family. Brocade will continue to offer and provide Hardware support for the EOA products five (5) years from the Last Customer Ship (LCS) announced below for those customers with a valid support contract subject to Brocade support policies.

The objective of the Brocade account management team is to assist you in making your final purchases of product subject to EOA and to smoothly transition to the new products by planning to the following milestones: :

FastIron SX switch fabric module and chassis bundles with the switch fabric module	Date
EOA Notification Date (EU Only)	January 28, 2016
Last Time Order (LTO) Final, Non-Cancelable, Non-Returnable Order Due Date (Subject to lead time and availability) (EU Only)	June 28, 2016
Last Customer Ship (LCS) Date (EU Only)	June 30, 2016
End of Support (EOS) Date (Hardware Only) (EU Only)	June 30, 2021

Brocade Part Number	Description	Recommended Alternative Solution
FI-SX1600-AC	FastIron SX 1600 modular chassis, one SX 1600 16-slot chassis, two Switch Fabric Modules, two system AC power supplies, 17 interface blank cover panels, six power supply cover panels , one air filter, and two fan trays.	No chassis replacement. Recommend ICX7450 or ICX7750 stacking solution as alternative product solution.
FI-SX1600-DC	FastIron SX 1600 modular chassis, one SX 1600 16-slot chassis, two Switch Fabric Modules, two system DC power supplies, 17 interface blank cover panels, six power supply cover panels , one air filter, and two fan trays.	No chassis replacement. Recommend ICX7450 or ICX7750 stacking solution as alternative product solution.
FI-SX800-AC	FastIron SX 800 modular chassis, one SX 800 8-slot chassis, two Switch Fabric module, one system AC power supply, nine interface panels, three power supply panels , and one fan tray.	No chassis replacement. Recommend ICX7450 or ICX7750 stacking solution as alternative product solution.
FI-SX800-DC	FastIron SX 800 modular chassis, one SX 800 8-slot chassis, two Switch Fabric module, one system DC power supply, nine interface panels, three power supply panels , and one fan tray.	No chassis replacement. Recommend ICX7450 or ICX7750 stacking solution as alternative product solution.
SX-FISF	FastIron SX modular series, Switch Fabric Module	No specific alternative solution.

## Replacement Products

Brocade recommends the ICX7450 and ICX7750 series as alternatives to the FastIron SX.

\*Additional restrictions and limitations apply to support for software and such support may be cancelled or changed without notice. Contact your sales representative for more information.